

# KTL - NEWSLETTER JUNE 2010

**Accidents – June Total = 0**

**Incidents – June Total = 5**

**Medical – June Total = 0**

**Near Misses – June Total = 34**

- City council member walked onto site without being inducted or signing onto JSSP. Was not spotted before entering.
- There was a cable in the ground 50mm covered in concrete. As operative was grading back he came into contact with duct but did not hit cable
- Cables damaged in the ground whilst hand digging.
- Crew standing on top of RBS and not wearing hard hats.
- Vehicle obstructing the road
- Steel not secured in steel equipment area
- Trailer wheel bolt indicators missing
- Operative not wearing ear defenders when using abrasive wheels
- Grass overgrown on site causing trip hazards
- Mirror on track machine was broken when it arrived on site
- Operative got sunburned on arms
- Operative nearly pinched his hand between two steel members while building the pylon
- Operative nearly caught finger when moving the generator that had come off the mount in three places
- Operative walking up to #317 slipped on the ash slope
- Piling rig set up on site, not set out properly
- While assembling the pylon - operative let a small steel member slip and fall on his steel toe cap boot
- Road Signage vandalised
- Operative was travelling to site when a lorry came round a bend on a narrow road
- Flashing Beacon not working on machine
- Operatives tripped over loose rebar
- Operative drove over harness that was left lying on the ground


## Recertification

**THE SUMMER COMMUNICATIONS MEETING AND BBQ WILL NOW TAKE PLACE ON FRIDAY 16<sup>TH</sup> JULY – EVERYONE IS REQUESTED TO ATTEND THIS IMPORTANT MEETING IN OUR NEW PREMISES.**


**PLEASE RETURN ALL YOUR HARNESES AND OTHER LIFTING EQUIPMENT TO THE OFFICE FOR RECERTIFICATION ON THIS DATE.**

**WE WILL ENDEAVOUR TO RETURN AS MUCH EQUIPMENT AS POSSIBLE BEFORE THE BBQ IS OVER.**

## Deviations in June



## Breakdown of deviations in June



## Safety in Pictures



Ensure certifications come with all KTL and hired machines and all drivers have their tickets on site with them. All machinery to be used in a safe manner at all times.



DO NOT PLACE YOUR LIFE OR THE LIVES OF OTHERS AT RISK. THE COST IS NOT WORTH IT.



All ladders must be tagged and fit for purpose. Any ladder which does not have an in-date tag then contact the safety department immediately.



Ensure a proper traffic management plan exists when working in public areas. Only trained personnel to set up the traffic management on public roads.



Special care must be taken when working near live electric lines. Ensure safe access to the work area at all times and that correspondence with ESB is in place if required. If unsure seek clarification before commencing work.

## Tools and Equipment Inspection



While turning off the angle grinder in the picture above the operators hand slipped and passed over the disc causing serious injury. When inspecting your work equipment ensure that there has been no alterations to place controls in an unsafe manner. Highlight any concerns to the plant manager.

## Recent audits

Last week KTL undertook surveillance audits for the ISO 19001 Quality System and the ISO 14001 Environmental System. We are pleased to say that KTL have maintained its certification



International Organization for Standardization